

Konfigurationer för låsbara kontaktdon

		15 A		20 A		30 A	
		Hona	Hane	Hona	Hane	Hona	Hane
2-pol	125 V						
	125 V						
	250 V						
2-pol+J	125 V						
	125 V						
	250 V						
	277 VAC						
	480 VAC						
	600 VAC						
	28 VDC						
	400 Hz 120 V						
3-pol	125/250 V						
	125/250 V						
	3Ø 250 V						
	3Ø 480 V						
	3Ø 600 V						
3-pol+J	125/250 V						
	3Ø 250 V						
	3Ø 480 V						
	3Ø 600 V						
	400 Hz 3ØΔ 120 V						
4-pol	3ØY 120/208 V						
	3ØY 277/480 V						
	3ØY 347/600 V						
4-pol+J	3ØY 120/208 V						
	3ØY 277/480 V						
	3ØY 347/600 V						
	400 Hz 3ØY 120/208 V						